

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 29

Township: 8 North


Range: 1 East

Corner ID: SaCr E-21

Monument Description & Remarks: 2" Aluminum cap, "MONROE COUNTY SURVEYOR" on 3/4" Rebar (Set) replacing disturbed Sandstone called out in L.S.B. no 2. Survey Sign 5ft above ground at pt. B

References On File: Legal Survey Book 2 page 225 survey (1873), on file in Surveyor Office


RECOVERY TIE DRAWING
Field Book 39 Page No. 63



- A - 2" Aluminum cap
- B - N 00° W 9.10' to Survey Sign on 4" Sugar Maple
- C - N 72° E 1.45' to MAG nail in 23" Chinquapin Oak
- D - S 43° W 11.57' to MAG nail in 20" White Oak

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 7th day of August, 2007



Administered by the Monroe County Surveyor Review Board

Date: 7/2/2010